



PO Box 1443
Buffalo, NY 14215
(716) 572-5358
art@amcoating.com
www.amcoating.com

American Coating Technologies was contacted by Main Care Energy to make a site visit at their Greenwich location, for the purpose of evaluating their secondary containment for the storage of fuel oil. Main Care had recently been inspected by the New York State Department of Environmental Conservation, and had a few areas which needed to be brought up to code.

Our project manager visited the site within days of the request. The review of the site revealed the containment would not meet current requirements so we proposed an engineering plan to replace the entire liner system.



The old system used high density polyethylene and after years of exposure to ultraviolet light and the harsh winters, the liner had failed.

We knew that the area was going to be re-inspected very soon, so we installed the entire liner system the following week.

This is the third Main Care Energy facility that we have upgraded in the last two years. Main Care Energy prides themselves on having their terminals operate at peak performance and use only the finest secondary containment systems available.

